




**Need Longer Liner / Piston Life?
Wish Your Pump Rods Lasted Longer?**

NEW! SPICKET™ Mud-Pump Rod Alignment Monitor



We Think We Have the Answer For You!

The most common reason for short rod, liner or piston Life is mis-alignment of Pump Rods. Whether due to a damaged rod or worn/cracked crossheads, mis-alignment of as little as 0.01mm (4 Thous.) can be accurately measured in twin axis and recorded for 3 rods simultaneously in about 3 minutes without dismantling anything. Now there's no excuse for not correcting problems before any damage occurs!



System consists of:-

- Two high-output sensors factory-fitted into each rod join link
- Screened signal cable connection to signal conditioner/amplifier
- Battery-powered portable Signal Conditioner/amplifier unit
- Notebook computer pre-calibrated with special plotting software for each type of pump
- Full instructions for installation/operation

Spicket Valves & Pumps Ltd., Lochwinnoch Rd., KILMACOLM, PA13 4TA, UK
Tel. +44 1505 874186 Fax +44 1505 874392 E-mail: spicketvalve@aol.com